

PATCH DOCUMENTATION

Change Log: e-Cast operator device (ET3400-T) and sensors (ET3400-WE)

Sensor Update: Version 1.03.00 (2017/07/17)

New hardware: new sensor available

Operator device update: Version 1.05.03/2.05.03 (2017/04/03)

Spelling mistakes have been corrected.

Operator device update: Version 1.05.02/2.05.02 (2017/02/21)

Spelling mistakes have been corrected.

Operator device update: Version 1.05.01/2.05.01 (2017/02/20)

Spelling mistakes have been corrected.

Operator device update: Version 1.05.00/2.05.00 (2017/01/26)

New: annual calibration

Sensor update: Version 1.02.17 (2015/09/08)

Fixed issue: minor errors when activating the sensors from sleep mode have been corrected.

The activation of the sensors from sleep mode has been improved.

New: annual calibration

Operator device update: Version 1.03.00 (2014/08/25)

New: selection of an orthosis side (left or right leg)

Operator device update: Version 1.02.00 (2014/07/10)

New: The new menu item "Delete measurements" has been added.

New: The ideal position can now be corrected and determined again.

Operator device update: Version 1.01.04 (2014/05/29)

Sensor update: Version 1.02.07 (2014/05/29)

The energy consumption during Sleep mode of the sensors has been improved.

Operator device update: Version 1.01.03 (2014/05/19)

Spelling mistakes have been corrected.

Operator device update: Version 1.01.02 (2014/04/24)

Sensor update: Version 1.02.06 (2014/04/24)

New: The device recognises a tremor.

Operator device update: Version 1.00.03 (2014/03/06)

Sensor update: Version 1.01.05 (2014/03/06)

Fixed issue: the sensors' energy consumption during measurements has been reduced.

New: the sensors' sleep mode, when the sensors are stored in certain positions, has been improved.

Operator device update: Version 1.00.02 (2013/12/04)

The USB functionality for Windows has been improved.

The measurement of the battery's state of charge has been improved.

New: the "new measurement" got a new sub-menu item for the selection of an orthosis type (KAFO, AFO or KO).

Operator device update: Version 1.00.01 (2013/10/18)

Fixed issue: the measurement of the battery's state of charge has been improved.

Better warning at very low battery's state of charge.

PATCH DOCUMENTATION

Change Log: NEURO TRONIC multi-purpose device (ET3830-T) and controller (ET3830)

Multi-purpose device update: Version 4.03.10 (2021.08.02)

Controller update: Version 2.85 (2021.08.02)

New: enable/disable detection of the first step

Multi-purpose device update: Version 4.03.09 (2021.01.25)

New: mode change setting (adjust the mode change setting for easier mode changing during movement)

Controller update: Version 2.84 (2021.01.25)

New: mode change setting (adjust the mode change setting for easier mode changing during movement)

Improvements: improved first step unlocking in auto mode

Multi-purpose device update: Version 4.03.08 (2020.11.12)

Improvements: bug fixes related to ET3830

Controller update: Version 2.83 (2020.11.12)

Improvements: bug fixes

Multi-purpose device update: Version 4.03.07 (2019.12.16)

New: code for troubleshooting

Improvements: bug fixes related to ET3830

Controller update: Version 2.82 (2019.12.16)

Improvements: bug fixes

Multi-purpose device update: Version 4.03.06 (2019.08.14)

Improvements: renewed icons, small bug fixes

Controller update: Version 2.81 (2019.08.14)

New: step counter for each mode (Free, Auto, Lock)

Multi-purpose device update: Version 4.03.05 (2019.05.15)

Controller update: Version 2.80 (2019.05.15)

New: rotation safety (adjust rotation safety for easier unlocking)

Multi-purpose device update: Version 4.03.02 (2018/11/21)

Controller update: Version 2.69 (2018/11/21)

Fixed issue: improved data processing in e-Motion

Multi-purpose device update: Version 4.03.01 (2018/11/08)

Controller update: Version 2.68 (2018/11/08)

Fixed issue: reduced sensitivity of mode change at standstill

Multi-purpose device update: Version 4.03.00 (2018/09/17)

New: mid stance settings, terminal swing settings

Controller update: Version 2.67 (2018/09/17)

New: mid stance settings, terminal swing settings, mode change only at standstill

Multi-purpose device update: Version 4.01.06 (2018/05/17)

Controller update: Version 2.66 (2018/05/17)

New: adjustable unlocking moment

Multi-purpose device update: Version 4.01.04 (2017/05/05)

No change, only a new version of the controller ET3830: v.2.65.

Controller update: Version 2.65 (2017/05/05)

Fixed issue: in Auto mode, the controller does no longer switch to Free mode when having a low battery status but remains locked.

Improved response to radio signals.

Multi-purpose device update: Version 4.01.03 (2014/12/22)

The signal function is now automatically switched on after an update.

Multi-purpose device update: Version 4.01.02 (2014/12/12)

The battery check during carrying out a controller update has been improved.

Controller update: Version 2.64 (2014/12/12)

Fixed issue: When sound settings were changed, the Auto mode sometimes did not respond any more.

Multi-purpose device update: Version 4.01.01 (2014/09/25)

Batteries have to be fully charged for an update.

Controller update: Version 2.61 (2014/09/25)

New: Signal function for p-Motion available.

Fixed issue: The calibration has been improved (signal filter).

The stability in e-Motion has been improved.

Multi-purpose device update: Version 4.01.00 (2014/09/10)

New: Signal function for p-Motion available.

Controller update: Version 2.60 (2014/09/10)

Fixed issue: The system joint switched from e-Motion to p-Motion unintentionally.

New: Settings will be saved on an external storage unit now (for higher reliability).

Rechargeable batteries of the controller have to be fully charged for an update.

The step count in e-Motion is saved more often.

Multi-purpose device update: Version 4.00.10 (2014/07/11)

Controller update: Version 2.52 (2014/07/11)

The controller calibration has slightly been adjusted.

The e-Motion technology has been improved.

Multi-purpose device update: Version 4.00.09 (2013/10/29)

Controller update: Version 2.50 (2013/10/29)

Shock detection was added to the controller for better resistance to shocks/hits.

Multi-purpose device update: Version 4.00.08 (2013/10/31)

Fixed issue: A wrong message was displayed when a user tried to update an old controller version that cannot be updated.

Minor spelling mistakes have been corrected.

Multi-purpose device update: Version 4.00.07 (2013/10/24)

Minor spelling mistakes have been corrected.

Change Log: NEURO TRONIC multi-purpose device (ET3840-T), controller (ET3830, ET3840, ET3845) and Remote Control (ET3840-P)

Multi-purpose device update: Version 5.03.10 (2021.08.02)

ET3830 Controller update: Version 2.85 (2021.08.02)

ET3840 Controller update: Version 3.00.48 (2021.08.02)

ET3845 Controller update: Version 3.00.48 (2021.08.02)

New: enable/disable detection of the first step

Multi-purpose device update: Version 5.03.09 (2021.01.25)

New: mode change setting (adjust the mode change setting for easier mode changing during movement)

ET3830 Controller update: Version 2.84 (2021.01.25)

New: mode change setting (adjust the mode change setting for easier mode changing during movement)

Improvements: improved first step unlocking in auto mode

ET3840 Controller update: Version 3.00.47 (2021.01.25)

New: mode change setting (adjust the mode change setting for easier mode changing during movement)

Improvements: improved first step unlocking in auto mode

Improvements: bug fixes

ET3845 Controller update: Version 3.00.47 (2021.01.25)

New: mode change setting (adjust the mode change setting for easier mode changing during movement)

Improvements: improved first step unlocking in auto mode

Improvements: bug fixes

Multi-purpose device update: Version 5.03.08 (2020.11.12)

Improvements: bug fixes related to ET3830

ET3830 Controller update: Version 2.83 (2020.11.12)

Improvements: bug fixes

Multi-purpose device update: Version 5.03.07 (2019.12.16)

New: code for troubleshooting

Improvements: bug fixes related to ET3830

ET3840-P Patient remote control update: Version 1.0.12 (2019.12.16)

Improvements: connection with controller

ET3830 Controller update: Version 2.82 (2019.12.16)

Improvements: bug fixes

Multi-purpose device update: Version 5.03.06 (2019.08.14)

Improvements: renewed icons, small bug fixes

ET3830 Controller update: Version 2.81 (2019.08.14)

ET3840 Controller update: Version 3.00.46 (2019.08.14)

ET3845 Controller update: Version 3.00.46 (2019.08.14)

New: step counter for each mode (Free, Auto, Lock)

Multi-purpose device update: Version 5.03.06 (2019.08.14)

ET3830 Controller update: Version 2.81 (2019.08.14)

ET3840 Controller update: Version 3.00.46 (2019.08.14)

ET3845 Controller update: Version 3.00.46 (2019.08.14)

New: step counter for each mode (Free, Auto, Lock)

Improvements: renewed icons and small bug fixes

Multi-purpose device update: Version 5.03.05 (2019.05.15)

ET3830 Controller update: Version 2.80 (2019.05.15)

ET3840 Controller update: Version 3.00.45 (2019.05.15)

ET3845 Controller update: Version 3.00.45 (2019.05.15)

New: rotation safety (adjust the protection against unintentional unlocking during rotation movements)

Multi-purpose device update: Version 5.03.04 (2019.01.23)

ET3840 Controller update: Version 3.00.42 (2019.01.23)

New: indication of bluetooth connection

ET3845 Controller update: Version 3.00.42 (2019.01.23)

New: indication of bluetooth connection

Multi-purpose device update: Version 5.03.03 (2018.12.17)

ET3840-P Patient remote control update: Version 1.0.11 (2018.12.17)

Fixed issue: unreliable connection with controller

Multi-purpose device update: Version 5.03.02 (2018/11/21)

Fixed issue: troubleshooting in the updating process

Fixed issue: menu item Battery Quality was sometimes not accessible

ET3830 controller update: Version 2.69 (2018/11/21)

Fixed issue: improved data processing in e-Motion

Multi-purpose device update: Version 5.03.01 (2018/11/08)

ET3830 controller update: Version 2.68 (2018/11/08)

ET3840 controller update: Version 3.00.41 (2018/11/08)

ET3845 controller update: Version 3.00.41 (2018/11/08)

Fixed issue: reduced sensitivity of mode change at standstill

Multi-purpose device update: Version 5.03.00 (2018/09/17)

New: mid stance settings, terminal swing settings

ET3830 controller update: Version 2.67 (2018/09/17)

ET3840 controller update: Version 3.00.40 (2018/09/17)

ET3845 controller update: Version 3.00.40 (2018/09/17)

New: mid stance settings, terminal swing settings, mode change only at standstill

ET3840-P Remote Control Update: Version 1.00.10 (2018/09/14)

LED signals have been updated according to the manual.

Multi-purpose device update: Version 5.00.06 (2018/05/17)

No change, only a new version of the controller ET3830: v.2.66.

ET3830 controller update: Version 2.66 (2018/05/17)

New: adjustable unlocking moment